

**APPENDIX B**

**SITE VISIT PHOTOGRAPHS**

**PARCEL 1**



Photo 1. William J. Blinn Trust Site – North of G-P Property.



Photo 2. William J. Blinn Trust Site – North of G-P Property.





Photo 3. Glass Beach #1.



Photo 4. Glass Beach #1.





Photo 5. Glass Beach #2.



Photo 6. Glass Beach #2.





Photo 7. Old Sewer Pipeline.



Photo 8. Soil Stockpiles on property leased by Pacific Marine Farms. Stockpiles have been removed.

**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 2**





Photo 1. Breezeway – Southeast Corner. Debris has been removed.



Photo 2. Storage Shed #2 – Surface stains underneath and around equipment.





Photo 3. Overhead transformer – Parcel 2.



Photo 4. Former USTs East of Storage Shed #2. USTs have been removed.





Photo 5. Drums and motor oil containers in Dowel Loc. Drums and motor oil containers have been removed.



Photo 6. Debris pile east side of Dowel Loc. Debris pile has been removed.





Photo 7. Surface staining on concrete in Glue Lam.



Photo 8. Cabinet and table northeast corner of Glue Lam. Cabinet and table have been removed.



**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 3**



Photo 1. View of Scrap Yard area. Debris has been removed.



Photo 2. Empty transformers in the Truck Loading Shed. Transformers have been removed.





Photo 3. One of two sand pits at Former Planer No. 1.



Photo 4. Former oil drum storage containing residual liquid in Former Planer No. 1 area. Liquid has been removed.





Photo 5. One of two transformer pads north of Former Planer No. 1.



Photo 6. View of interior of Dry Shed No. 4.





Photo 7. View of exterior of Dry Shed No. 5 (Dry Shed No. 4 on left side).



Photo 8. Catch basin (foreground) and sump (background) south of Former Mobile Equipment Shop.





Photo 9. Building foundation and metal pipe with hydrocarbon odor at Former Mobile Equipment Shop.



Photo 10. Open storage area in Construction Engineering. Debris has been removed.





Photo 11. Paint storage in Construction Engineering. Paint supplies have been removed.



Photo 12. View of Kilns.



Photo 13. Air compressor and several drums in Compressor House 1. Air compressor and drums have been removed.



Photo 14. Oil storage in Compressor House 2. Oil and containers have been removed.





Photo 15. Staining from air compressor lines outside Machine Shop (foreground) and Sheet Metal/Plumbing building (background).




Photo 16. Sump no longer in use at Machine Shop.



Photo 17. Oil storage in metal container in Sheet Metal/Plumbing.



Photo 18. Paint containers outside Plant Supply. Oxygen, argon, and carbon dioxide in locked shed in background. Containers and debris have been removed.



**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 4**



Photo 1. Three 10,000-gallon reserve fuel tanks at the power house fuel storage shed. Fuel tanks have been removed.



Photo 2. Location of former bunker fuel oil ASTs and associated railroad tracks. Note the water treatment plant on the left hand side.





Photo 3. Chemical tanks (sodium hypochlorite and alum) in water treatment plant. Tanks have been removed.



Photo 4. View of water treatment plant and cement AST.



Photo 5. North settling pond with thick vegetation.



Photo 6. Collection Pond in the west area of Parcel 4.





Photo 7. View of south settling pond. Note the fuel barn on the left side.



Photo 8. East end of south settling pond with visible sheen on the water.



Photo 9. View of northeast side of power house.



Photo 10. Paint storage shed on the south side of the power house. Paint and supplies have been removed.





Photo 11. Transformer pad on the north side of the power house.



Photo 12. Inside oil storage shed. Oil and containers have been removed.



Photo 13. Location of former sugar cane press in southwest corner of press building.



Photo 14. View of the cooling towers. Chemical tanks and shed are located on the other side of cooling towers building.





Photo 15. View of log pond on Parcel 4 looking southwest.

**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 5**





Photo 1. Fuel Storage and Dispenser Building.



Photo 2. Concrete conduit in Fuel Storage and Dispenser Building with fuel pipes.



Photo 3. ASTs located inside Fuel Dispenser and Storage Building. ASTs have been removed.



Photo 4. Staining within concrete berm inside Fuel Dispenser and Storage Building.





Photo 5. Location of former Sawmill #1.



Photo 6. Mendocino County Hospital Office Buildings located along Highway 1.



Photo 7. Oil Change Pit located within Mobile Equipment Shop.




Photo 8. Oil Change Pit.





Photo 9. Covered Pit located inside Mobile Equipment Shop.



Photo 10. Engines stored in Mobile Equipment Shop (some surface staining). Engines have been removed.






Photo 11. North Shed – Mobile Equipment Shop.



Photo 12. West Shed – Mobile Equipment Shop.





Photo 13. Steam Pipe insulation.



Photo 14. Eastern Side of Mobile Equipment Shop.



Photo 15. Western Side of Mobile Equipment Shop.



Photo 16. Area West of Mobile Equipment Shop – Possible old AST location





Photo 17. Tire Shop Building.



Photo 18. Inside Tire Shop Building



Photo 19. Washdown and Repair Building.



Photo 20. Washdown and Repair Building – Soil Stockpile. Soil Stockpile has been removed.





Photo 21. Transformer Pad located near small pond.

**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 6**





Photo 1. Concrete pad at former Cooling Towers location (looking northeast).



Photo 2. Air compressor located in the central area of Planer Mill No. 2.



Photo 3. Transformer located in the central area of Planer Mill No. 2.



Photo 4. Stained concrete and soil outside the central area of Planer Mill No. 2.





Photo 5. Shipping Office.



Photo 6. Estimated area of former fuel pump and diesel storage northeast of the Shipping Office, in the background.

**APPENDIX B**

**SITE VISIT PHOTOGRAPHS**

**PARCEL 7**





Photo 1. View of Sawmill No. 2 looking east.



Photo 2. South Ponds on Parcel 7.



Photo 3. Sediment storage area.



Photo 4. One of four groundwater wells along the east area of Parcel 7.





Photo 5. Transformers north of Sawmill No. 2.

**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 8**





Photo 1. Clunker Piles.



Photo 2. Airstrip.

**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 9**





Photo 1. Air Compressor inside Main Packing Shed.



Photo 2. Holding Tank, pump house, and chemical storage shed.



Photo 3. Water filtration and purification system tanks. Tanks have been removed.



Photo 4. Chemical mixing shed.





Photo 5. Scrap Metal Area.

**APPENDIX B**  
**SITE VISIT PHOTOGRAPHS**  
**PARCEL 10**






Photo 1. Coastline of Disturbed Area .



Photo 2. Clinkers and suspect fill material along coastline of Parcel 10.





Photo 3. Wood debris and clinkers emanating from soil along coastline of Parcel 10.



Photo 4. Clinkers and wood debris along coastline of Parcel 10.





Photo 5. Blowhole on Parcel 10 – Scrap iron present in lower left corner.



Photo 6. Discoloration along western wall of Blowhole.





Photo 7. Western wall of Blowhole – Slight discoloration of walls and suspect debris fill material present.